

FIG. 1

FIG. 2(A)




FIG. 2(B)





FIG. 3(A)



H-12b


H-11


FIG. 3(B) Collective wire measuring C12 Collective pressure contact of wires H-12a C13 C12 Collective

H-12a

wire cutting and terminal crimping and insertion

## FIG. 4(A)










FIG. 5 (PRIOR ART)








FIG. 8 (PRIOR ART)